


Activity Analysis Part 2 | Cross Walks



- Cross walks with no signage or light signal
- Cross walks with light signal

Quantifying the amount of marked crosswalks with no signage or light signal in the downtown core region amounted amounted to a total of 32 crosswalks. Whereas quantity of marked crosswalks with a light signal was 40. Additionally, a total of 6 cross walks are unprotected if a motorist is making a left turn at an intersection and does not see a pedestrian crossing as he/she makes that turn.

